






TOYOTA LANDCRUISER - 4WD

HDJ100, HZJ100, UZJ100 I.F.S. Station Wagon

4/1998 to 11/2007

Part and Location	Description	Approx Lift	Part Number	Qty Per Vehicle
SHOCK ABSORBERS				
	35mm Gas Bulged Shock Absorbers - Piranha		SA35103GP	2 ea
TORSION BARS				
	Increased Rate Torsion Bars Length 1160mm Petrol		TOY041	1 pr
	Increased Rate Torsion Bars Length 1210mm Diesel / Turbo Diesel / 6 Cylinder Petrol Engine		TOY041D	1 pr
TORSION BAR SUPPORT BRACKET				
	Torsion Bar Support Bracket		TOY041SUPPBKT	1 kit
SHOCK ABSORBERS				
	35mm Gas Bulged Shock Absorbers - Piranha		SA35104GP	2 ea
COIL SPRINGS				
	Raised Height Heavy Duty Coil Springs Progressive Rate - LBA 50kg to GVM	STD	TLC-210	1 pr
	Raised Height Heavy Duty Coil Springs Progressive Rate - LBA up to 150kg	20mm	TLC-209	
	Raised Height Heavy Duty Coil Springs LBA up to 200kg	25mm	TLC-217	
	Raised Height Extra Heavy Duty Coil Springs LBA 250kg Plus - constant load	25mm	TLC-216HD	

F
R
O
N
T

R
E
A
R

* LBA = Load Bearing Accessories (Bull Bar, Winch, Tyre Carrier, Extra Fuel Tanks etc)