





# HYUNDAI TERRACAN - 4WD

HP 11/2001 - 12/2007

Part and Location	Description	Approx Lift	Part Number	Qty Per Vehicle	
<b>SHOCK ABSORBERS</b>					<b>F R O N T</b>
	35mm Gas Bulged Shock Absorbers		TBA	2 ea	
<b>TORSION BARS</b>					<b>F R O N T</b>
	Increased Rate Torsion Bars Length 1275mm		HYUN004	1 pr	
<b>SHOCK ABSORBERS</b>					<b>R E A R</b>
	35mm Gas Bulged Shock Absorbers		TBA	2 ea	
<b>COIL SPRINGS</b>					<b>R E A R</b>
	Raised Height Medium Duty Coil Springs	40mm	MIT-201	1 pr	